AMENDMENTS TO THE CLAIMS

This listing of claims will replace all prior versions, and listings, of claims in the application.

Listing of Claims:

- 1. (Currently Amended) A clothes dryer comprising:
- a base forming a floor of a body;
- a front cabinet forming a front portion of the body;
- a side cabinet forming side portions of the body;
- a back cover forming a back portion of the body;
- a control panel having a hook; [[and]]
- a top cover forming a top of the body wherein the top cover has a predetermined curvature, and wherein the control panel is provided on a rear portion of the top cover, the top cover comprising a groove provided at a rear portion of the top cover wherein the hook is disposed in a surface of the control panel opposite the top cover such that the hook inserts into a hole disposed in the groove; and
- a fire wall made of metal disposed at a lower portion of the top cover, and the fire wall directing a fluid toward an outside of the body if fluid leaks through the hole.
- 2. (Previously Presented) The clothes dryer of claim 1, wherein the firewall has the same predetermined curvature.

Application No.: 10/663,997 Amdt. dated April 27, 2006

action No.: 10/663,997 Docket No.: 9988.058.00

3. (Currently Amended) The clothes dryer of claim 1, wherein the groove is

provided in left and right directions along a rear side of the top cover and the groove has the

same predetermined curvature.

4. (Currently Amended) A laundry dryer comprising:

a body;

a top cover covering the body, the top cover including:

a groove which runs along a width of the top cover wherein the groove directs fluid on

the top cover toward an exterior of the laundry dryer;

at least one hole disposed in the groove; [[and]]

a control panel including a hook disposed at a surface of the control panel opposite the

top cover wherein the hook is configured for insertion into the at least one hole; and

a fire wall disposed below the top cover; wherein the firewall has a curvature such that if

a fluid leaks through the hole onto the firewall, the fluid is directed toward an outside of the

body.

5. (Previously Presented) The laundry dryer of claim 4, wherein the top cover has a

curvature.

6. (Canceled)

3